	Land	llord Gas S	Safety Cer	tificate	Page No	1 of 1	
HAFOD HEATING HEATING AND PLUMBING			/ -		Ref:		GAS 👝 💿
	Date:	20/02/2025	Unique Serial No:	33503	Gas Safe Reg No:	664438	
			-				REGISTER

H

	Customer Address			Site Details		Registered Business Details			
Name:	Mr David Bannister		Name:	Mike Dutton		Name:	Hafod Heating Ltd		
	22 Abbottsford Drive			11 Tai Maes			6 Hafod Y Wern		
Address:	ress:		Address:			Address:			
	Chester			Mold			Mold		
Postcode:	CH4 0JG		Postcode:	CH7 1RW		CH7 1RW		Postcode:	CH7 5ND
Telephone:	Mobile:	07711478667	Telephone:	Mobile:		Telephone:	07500801819		

	Appliance Details							Inspection Details									
	Location	Appliance Type	Make	Model	Flue Type	Landlord's Appliance (if applicable) Yes/No/NA	Appliance Inspected Yes/No	Operating Pressure in mbars or heat input kW/h	Safety device(s) correct operation Yes/No	Ventilation provision satisfactory Yes/No	Spillage Test Pass / Fail / NA	Smoke Pellet Flue Flow Test Pass / Fail / NA	Satisfactory Termination Pass / Fail / NA	Flue Visual Condition Pass / Fail / NA	Appliance serviced Yes/No	Appliance safe to use Yes/No	
1	Kitchen	Combi Boiler	Baxi	Performa 28	RS-FF	Yes	Yes	12.00 mbar	Yes	Yes	Na	Na	Pass	Pass	Yes	Yes	
2																	
3																	
4																	
5																	

	Defects Identified	Combustion Analysis Readings									
			1st Re	ading Mi	n/Low	2nd Readings/Max/High			3rd Reading DHW		
			СО	CO2	Ratio	СО	CO2	Ratio	СО	CO2	Ratio
1			9	3.3	0.0003	17	6.6	0.0003	17	6.6	0.0003
2											
3											
4											
5											

Final Checks								Sign-Off		Flue Types Key
Gas Tightnes		20.	.00	TT final val	ue:	20.00				FL-Flueless
valu	ue:						This safety record is issued	HTILDA		OF-Open Flue
	Satisfactory gas tightness test Yes/No/NA:					Yes	by:			RS-BF-Room sealed balanced flue
Gas installation pipework satisfactory visual inspe									RS-FF-Room sealed fan flue	
	Emergency Control accessible Yes/No:					Yes	Gas Operative	Steve Williams		NEXT SAFETY CHECK DUE BEFORE 20/02/2026
Mair	Main Protective Equipotential Bonding satisfactory Yes/No:					No				
CO alarm present?	Yes	CO alarm working?	Yes	In date?	Ye	es		Date	20/02/2025	
Smoke alarm	Smoke alarm(s) present? Yes Smoke alarm(s) working?				Ye	es	Received by	Customer is not present	.	
This inspection is for gas safety purposes only in accordance with the Gas Safety(Installation and Use) Regulations.Flues were visually inspected and checked satisfactory evacuation of products of combustion.A detailed internal inspection of					d check		,	Customer is not present	L	
	flue integrity, construction and lining has not been carried out.					or the	Name	Mike Dutton		This certificate was produced using the TradeHelp app